

STATE OF FLORIDA
DEPARTMENT OF HEALTH
COUNTY HEALTH DEPARTMENT
PUBLIC SCHOOL
INSPECTION REPORT



2 of 2

General Comments

Facility s working on Campus maintenance.

Email Address(es): jenriquez@dadeschools.net;
jware@dadeschools.net;
ipalacio@dadeschools.net;
jaybolton@dadeschools.net

Violations Comments

Violation #5. Maintenance & Repair
Stained ceiling' panels in: Room # 1208, and Room #1215.
Replace stained ceiling' panels.

Biological built up on HVAC exhaust filter system in: Room # 1208, Room # 1301, and Room # 1307.
Clean HVAC exhaust filter system.

CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair.

Inspection Conducted By: Alberto Reyes (913936)
Inspector Contact Number: Work: (305) 623-3500 ex.
Print Client Name:
Date: 8/7/2019

Inspector Signature:

Handwritten signature of Alberto Reyes.

Client Signature:

Handwritten signature of Jose Marti.