STATE OF FLORIDA DEPARTMENT OF HEALTH **COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT**



1 of 3

Facility Information

Permit Number: 13-51-08353 Name of Facility: Jose Marti MAST 6-12 Academy Address: 5701 W 24 Avenue City, Zip: Hialeah Gardens 33016

Type: Public Schools Owner: MDCPS Person In Charge: M-DCSB Food and Nutrition Phone: (786) 275-0400 PIC Email: jenriquez@dadeschools.net

Inspection Information

Purpose: Routine Inspection Date: 6/13/2025

Additional Information

FEMALES 477 MALES 564

This form serves as a "Notice of Non-Compliance" pursuant to section 120.695, Florida Statutes. Items marked below violate one or more of the requirements of Rule 6A-2.0010, of the Florida Administrative Code, Chapter 5, section 5 of the State Requirements for Educational Facilities 2014 (SREF); and sections 453 and 468 of the Florida Building Code 6th Edition (2017). Violations must be corrected within the time period indicated above. Continued operation of this facility without making these corrections is a violation. Failure to correct violations in the time frame specified may result in enforcement action being initiated by the Department of Health.

Violation Markings

| SCHOOL SANITATION | IN 11. Group Toilet Rooms | IN 21. Pest Control |
|--|-----------------------------------|--------------------------------------|
| I. School Site | IN 12. Toilet Facilities | SAFETY |
| IN 2. Playground, Equip & Athletic Fields* | IN 13. Handwashing Facilities | IN 22. First Aid Kit |
| IN 3. Athletic & Playground Equipment | IN 14. Soap Dispensers | DIAPER CHANGING STATION |
| BUILDING CONST/MAINT. | IN 15. Shower Facilities | NA 23. Sanitizers |
| IN 4. Construction | NA 16. Showers Water Temperatures | NA 24. Changing Station & Mats |
| OUT 5. Maintenance & Repair | WATER SUPPLY | NA 25. Hand Sink |
| OUT 6. Lighting Standards | IN 17. Approved Source | NA 26. Garbage Can |
| IN 7. Heating, Ventilation, A/C Standards | IN 18. Drinking Fountains | ANIMAL HEALTH & SAFETY |
| IN 8. Natural Ventilation | LIQUID WASTE & WASTE WATER | NA 27. Animal Maintenance/Aggressive |
| IN 9. Mechanical Ventilation | IN 19. Sewage Disposal | DORM/RESIDENTIAL FACILITIES |
| SANITARY FACILITIES | IN 20. Solid Waste | NA 28. Maintenance/Complaint |
| IN 10. Provided/Accessible/Separation | PEST CONTROL | NA 29. Other |

Marking Key: IN = the act or item was observed to meet standards; OUT = the act or item was observed not to meet standards; NO = the act or item was not observed to be occuring at the time of inspection; NA = the act or item is not performed by the facility or not part of the operation

Violation Key: * = 2. Playground, Equipment & Athletic Fields

Inspector Signature:

KL.

Client Signature:

XA

Form Number: DH 4030 12/16A

13-51-08353 Jose Marti MAST 6-12 Academy

RESULT: Satisfactory

Correct By: Next Inspection Re-Inspection Date: None

Begin Time: 12:20 PM End Time: 02:10 PM

CENSUS 1041

STATE OF FLORIDA DEPARTMENT OF HEALTH COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT



2 of 3

General Comments

Group Inspection: Jose Enriquez Jr. (Principal). Maite Roble (Assistant Principal). Juliet A. Olivera (Principal Secretary) signed the inspection. Summer Section: At the time of inspection: Linda Cespedes (Head Custodian), assisted with inspection. No shower(s) in the Clinic. Shower(s) in PE Locker Rooms (at the time of inspection, water faucets (hot/cold) in PE showers were closed/Summer Camp). Provide water in showers at a minimum temperature of 95°F; in a temperature range not less than 95°F and not more than 110°F). Email Address(es): jenriquez@dadeschools.net; mjerez@dadeschools.net; copyqueen@dadeschools.net; wcabrera@dadeschools.net; mwertz@dadeschools.net; ipalacio@dadeschools.net;

Inspector Signature:

M

Client Signature: LAD

Form Number: DH 4030 12/16A 13-51-08353 Jose Marti MAST 6-12 Academy

STATE OF FLORIDA DEPARTMENT OF HEALTH **COUNTY HEALTH DEPARTMENT PUBLIC SCHOOL INSPECTION REPORT**



3 of 3

Violations Comments

Violation #5. Maintenance & Repair Observations: Stains on Ceiling Panels: 1. Room # 2104 (one (1) stained ceiling panel). 2. Room # 1123 (eleven (11) stained ceiling panels). 3. Room # 1119 (ten (10) stained ceiling panels). Replace all stained ceiling panels. CODE REFERENCE: 5. Maintenance and Repair. 5(1)(e)8.h SREF. Light fixtures and window surfaces, both inside and outside, shall be kept clean, serviceable, and in good repair at all times. 5(1)(e)8.i. Custodial areas shall be kept clean, safe, and orderly at all times. Custodial equipment shall be in good repair at all times. 5(1)(e)8.j SREF. Building components & finishes shall be kept clean & in good repair. Violation #6. Lighting Standards Observations: Burnt-Out Light Bulb(s) in Lamps: 1. Room # 1123 (one (1) Lamp with one (1) burnt-out light bulb: FC: 11.32). 2. Room # 1117 (three (3) Lamps with one (1) burnt-out light bulb in each Lamp: FC: 16.98). 3. Room # 1115 (seven (7) Lamps with one (1) burnt-out light bulb in each Lamp: FC: 17.8). 4. Room # 1208 (two (2) Lamps with one (1) burnt-out light bulb in each Lamp: FC: 10.45). 5. Room # 1226 (four (4) Lamps with one (1) burnt-out light bulb in each Lamp: FC: 25.52). 6. Boys Gym (six (6) Lamps with one (1) burnt-out light bulb in each Lamp: FC: 23.4). Replace all burnt-out light bulbs in each Lamp. CODE REFERENCE: 6. Lighting Standards. 468.3.2. FBC. Sources of natural light in instructional spaces shall be glazed with glare reducing materials or shall be shielded to prevent glare that can interfere with seeing task.

Inspection Conducted By: Alberto Reyes (032763) Inspector Contact Number: Work: (305) 623-3500 ex. Print Client Name: Juliet A. Olivera (Principal Secretary). Date: 6/13/2025

Inspector Signature:

Client Signature:

AR AS

Form Number: DH 4030 12/16A 13-51-08353 Jose Marti MAST 6-12 Academy